Search Notes

Application/Control No.	Applicant(s)/Patent under Reexamination
10/771,083	HOFMEISTER ET AL.
Examiner	Art Unit
Toan M. Le	2863

SEARCHED				
Class	Subclass	Date	Examiner	
702	120	5/24/2005	TL	
372	38.1	5/12/2005	TL	
372	50	5/12/2005	TL	
257	688	5/20/2005	TL	
385	92	5/20/2005	TL	
385	93	5/20/2005	TL	
372	38.02	5/23/2005	TL	
Above	Updated	12/22/2005	TL	
Above	Updated	7/21/2006	TL	
398	135	7/21/2006	TL	

INT	INTERFERENCE SEARCHED				
Class	Subclass	Date	Examiner		

SEARCH NOTES (INCLUDING SEARCH STRATEGY)				
	DATE	EXMR		
Electrostatic Discharge Damage, Photodiode, Laser	5/12/2005	TL		
Laser Diode, Switch, Transceiver, Pins	5/12/2005	TL		
Transceiver Module, Laser Diode	5/12/2005	TL		
VCSEL, Laser Drive, Laser Diode, Transceiver	5/23/2005	TL		
702/120; 372/38.1,38.02; 257/688; 398/135 (Laser Diode)	7/21/2006	TL		
East-See Search History Printout	7/21/2006	TL		
IEEE Xplore, Web	7/21/2006	TL		